

Product Group: DCA-SERIES

Model: DCA John Deere Models

The information and specifications included in this publication were in effect at the time of approval for printing. Illustrations, descriptions, references and technical data contained in this document are for guidance only and may not be considered as binding. Multiquip Inc. reserves the right to discontinue or change specifications, design or the information published in this publication at any time without notice and without incurring any obligations.

John Deere 4045, 6068, 6090 LIGHT LOAD EGR VALVE & COOLER SOOT DEPOSITS

WORK SAFELY!

ULTIQUIP

Only a qualified service technician with proper training should perform this procedure. Follow all shop safety rules while performing this procedure.





John Deere Tier 4 Final & 4 Interim engines may experience heavy Unburnt Fuel (**Soot**) deposits in the Exhaust Gas Recirculation (**EGR**) Valve & Cooler due to Light Loading situations, thus causing the specific EGR fault codes: SPN 2659 FMI 1 or 18- NOx Based EGR Flow Correction Low.

Normal EGR Valve & Cooler Operation in the System

• The EGR valve opens so exhaust gas can recirculate back into the intake manifold. This lowers combustion temperatures and, therefore, lowers oxides of Nitrogen (NOx) emissions.

Effects on EGR system in Light Loading Situations

- The ECU derates the engine.
- EGR flow measured by pressure differential is significantly higher than EGR flow measured by temperature differential, and the EGR flow correction factor has reached the minimum limit.
- Soot deposits begin accumulating in the EGR valve & Cooler.
- Poor Engine Performance.
- NOx Emissions related fault codes
- Low DOC outlet temp. during a regeneration process.

ECU's Fault Detection of EGR System

The valve is opened by the ECU when the engine is at operating temperature and under load.
The valve is located at the entrance of the intake manifold, where exhaust gas and intake air are
mixed. The valve is normally closed. If the Valve fails to open when meeting the desired engine
temperature, a fault will come active.



Product Group: DCA-SERIES

Model: DCA John Deere Models

The information and specifications included in this publication were in effect at the time of approval for printing. Illustrations, descriptions, references and technical data contained in this document are for guidance only and may not be considered as binding. Multiquip Inc. reserves the right to discontinue or change specifications, design or the information published in this publication at any time without notice and without incurring any obligations.

John Deere 4045, 6068, 6090 LIGHT LOAD EGR VALVE & COOLER SOOT DEPOSITS

Corrective Action for EGR Valve and Emission related fault codes.


- 1. Remove the valve to clean off the deposits, (one electrical plug and 3 bolts), (1 Band-Clamp on cooler side for easy cooler inspection. (Note: Gaskets can be reused), Ref. Fig. 1 & 2.
- 2. Remove unwanted deposits using a flat blade screwdriver. Once deposits have been cleared, confirm the butterfly valve moves freely.
- 3. These EGR faults will self-clear at the next power (operator key or toggle switch) cycle if the valve motor is able to operate properly. (NOTE: If EGR Valve requires replacement, the new valve needs to be calibrated via engine software.)

PLEASE NOTE:

4ULTIQUIP

REMOVE AND INSPECT THE EGR VALVE & EGR COOLER FLEX PIPING AT 750 HOURS AS PART OF A STANDARD MAINTENANCE SCHEDULE.


Fig. 1



Legend

- A Electrical Connector
- B Electric Motor
- C Clutch Housing
- D Butterfly
- E Motor Shaft

Fig. 2



Legend

 $\begin{array}{lll} A-Gasket & H-Nuts~(2) \\ B-EGR~Valve & I-Heat~Shield \\ C-EGR~Valve~to & J-Spacer \\ & Venturi~Pipe & K-Clamp \end{array}$

D – EGR Cooler to L – Exhaust Manifold
EGR Valve Pipe Pressure Sensor Connection

E - Cap Screw (3) M - Cap Screw

F – EGR Bracket N – Nut

G – Sensor Bracket O – Exhaust Manifold Pressure Sensor



Product Group: DCA-SERIES

Model: DCA John Deere Models

The information and specifications included in this publication were in effect at the time of approval for printing. Illustrations, descriptions, references and technical data contained in this document are for guidance only and may not be considered as binding. Multiquip Inc. reserves the right to discontinue or change specifications, design or the information published in this publication at any time without notice and without incurring any obligations.

John Deere 4045, 6068, 6090 LIGHT LOAD EGR VALVE & COOLER SOOT DEPOSITS

EGR Cooler internal inspection


MULTIQUIP

When suspecting an EGR Cooler with soot buildup or an internal rupture, it is recommended removing the flex elbow piping for easy access to complete a visual inspection.

- Check for active or stored low coolant codes or low surge tank. If coolant loss is visible or DTC history indicates coolant loss, inspect for external leaks.
- Pressure test cooling system while inspecting for additional coolant buildup in the EGR cooler.
- **Note:** If EGR cooler is failed and a new cooler is installed, load banking is recommended, 2 hours of operation at a load of 75% of the generator's nameplate rating to verify engine reliability.
- Ensure to bleed coolant system at highest engine point after repairs.

If there is no coolant loss or low coolant DTC's, <u>DO NOT</u> replace the EGR cooler unless extreme soot buildup is present.

Due to the cooler efficiency, condensation will build in the cooler that is often mistaken as coolant. The condensation has a <u>yellow tint - this is not</u> coolant.



Clean Cooler with Condensation



Dirty Cooler with Condensation



Condensation in Water Bottle for Visual