




Service Bulletin

AR13HAR Honda Engine Recall

Product Group: Rollers	Date Issued: 09/04/12	Service Bulletin No. RR20120904
Bulletin Type <input type="checkbox"/> Mandatory <input checked="" type="checkbox"/> Information Only <input type="checkbox"/> Recommended Change		Models/Series Affected: AR13HAR Various

Details Problem: The engine may have an ignition coil malfunction, causing the engine to run on one cylinder. The engine may appear to run, but when a heavy load is applied, the engine may stop running. Solution: Stop using your roller and contact a servicing Honda Engine dealer. Your engine warranty is covered by Honda.

Procedure: 1. Inspect your engine serial number (Figure 1) and compare it to the list of affected serial numbers (Table 1).																																									
	<table border="1" style="width: 100%; text-align: center;"> <thead> <tr> <th colspan="4">Table 1. Honda GX630 Engines Affected Serial Numbers</th> </tr> </thead> <tbody> <tr><td>GCBEK-1057905</td><td>GCBEK-1057935</td><td>GCBEK-1059578</td><td>GCBEK-1059617</td></tr> <tr><td>GCBEK-1057919</td><td>GCBEK-1057936</td><td>GCBEK-1059582</td><td>GCBEK-1059618</td></tr> <tr><td>GCBEK-1057920</td><td>GCBEK-1057937</td><td>GCBEK-1059587</td><td>GCBEK-1059619</td></tr> <tr><td>GCBEK-1057921</td><td>GCBEK-1057938</td><td>GCBEK-1059590</td><td>GCBEK-1059620</td></tr> <tr><td>GCBEK-1057922</td><td>GCBEK-1057939</td><td>GCBEK-1059593</td><td>GCBEK-1059621</td></tr> <tr><td>GCBEK-1057923</td><td>GCBEK-1057940</td><td>GCBEK-1059598</td><td>GCBEK-1059622</td></tr> <tr><td>GCBEK-1057924</td><td>GCBEK-1057941</td><td>GCBEK-1059601</td><td>GCBEK-1059623</td></tr> <tr><td>GCBEK-1057925</td><td>GCBEK-1059575</td><td>GCBEK-1059616</td><td>GCBEK-1063660</td></tr> <tr><td>GCBEK-1057926</td><td></td><td></td><td></td></tr> </tbody> </table>	Table 1. Honda GX630 Engines Affected Serial Numbers				GCBEK-1057905	GCBEK-1057935	GCBEK-1059578	GCBEK-1059617	GCBEK-1057919	GCBEK-1057936	GCBEK-1059582	GCBEK-1059618	GCBEK-1057920	GCBEK-1057937	GCBEK-1059587	GCBEK-1059619	GCBEK-1057921	GCBEK-1057938	GCBEK-1059590	GCBEK-1059620	GCBEK-1057922	GCBEK-1057939	GCBEK-1059593	GCBEK-1059621	GCBEK-1057923	GCBEK-1057940	GCBEK-1059598	GCBEK-1059622	GCBEK-1057924	GCBEK-1057941	GCBEK-1059601	GCBEK-1059623	GCBEK-1057925	GCBEK-1059575	GCBEK-1059616	GCBEK-1063660	GCBEK-1057926			
Table 1. Honda GX630 Engines Affected Serial Numbers																																									
GCBEK-1057905	GCBEK-1057935	GCBEK-1059578	GCBEK-1059617																																						
GCBEK-1057919	GCBEK-1057936	GCBEK-1059582	GCBEK-1059618																																						
GCBEK-1057920	GCBEK-1057937	GCBEK-1059587	GCBEK-1059619																																						
GCBEK-1057921	GCBEK-1057938	GCBEK-1059590	GCBEK-1059620																																						
GCBEK-1057922	GCBEK-1057939	GCBEK-1059593	GCBEK-1059621																																						
GCBEK-1057923	GCBEK-1057940	GCBEK-1059598	GCBEK-1059622																																						
GCBEK-1057924	GCBEK-1057941	GCBEK-1059601	GCBEK-1059623																																						
GCBEK-1057925	GCBEK-1059575	GCBEK-1059616	GCBEK-1063660																																						
GCBEK-1057926																																									
Figure 1. Engine Serial Number	2. If your engine serial number is on the list, do the following: <ol style="list-style-type: none"> a. Stop using your roller and contact a servicing Honda Engine dealer (mention GX630 engine recall) to make an appointment to have the ignition coils inspected and, if necessary, replaced free of charge. Transportation of the equipment to the dealer is the responsibility of the owner. b. If you need assistance locating a servicing Honda Engine dealer, please visit their web site: www.engines.honda.com. or contact them at (888) 888-3139. 																																								



Service Bulletin

AR13HAR Honda Engine Recall

HERE'S HOW TO GET HELP

PLEASE HAVE THE MODEL AND SERIAL
NUMBER ON-HAND WHEN CALLING

UNITED STATES

Multiquip Corporate Office

18910 Wilmington Ave. Tel. (800) 421-1244
Carson, CA 90746 Fax (310) 537-3927
Contact: mq@multiquip.com

Service Department

800-421-1244 Fax: 310-537-4259
310-537-3700

Technical Assistance

800-478-1244 Fax: 310-943-2238

MQ Parts Department

800-427-1244 Fax: 800-672-7877
310-537-3700 Fax: 310-637-3284

Warranty Department

800-421-1244 Fax: 310-943-2249
310-537-3700

MEXICO

MQ Cipsa

Carr. Fed. Mexico-Puebla KM 126.5 Tel: (52) 222-225-9900
Momoxpan, Cholula, Puebla 72760 Mexico Fax: (52) 222-285-0420
Contact: pmastretta@cipsa.com.mx

CANADA

Multiquip

4110 Industriel Boul. Tel: (450) 625-2244
Laval, Quebec, Canada H7L 6V3 Tel: (877) 963-4411
Contact: jmartin@multiquip.com Fax: (450) 625-8664

UNITED KINGDOM

Multiquip (UK) Limited Head Office

Unit 2, Northpoint Industrial Estate, Tel: 0161 339 2223
Globe Lane, Fax: 0161 339 3226
Dukinfield, Cheshire SK16 4UJ
Contact: sales@multiquip.co.uk

© COPYRIGHT 2012, MULTIQUIP INC.

Multiquip Inc and the MQ logo are registered trademarks of Multiquip Inc. and may not be used, reproduced, or altered without written permission. All other trademarks are the property of their respective owners and used with permission.

The information and specifications included in this publication were in effect at the time of approval for printing. Illustrations, descriptions, references and technical data contained in this document are for guidance only and may not be considered as binding. Multiquip Inc. reserves the right to discontinue or change specifications, design or the information published in this publication at any time without notice and without incurring any obligations.

Your Local Dealer is:

