This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

PART EM20705 RELAY SUBSTITUTION

The purpose of this TI document is to inform of a substitution for relay part #EM20705 with kit part #EM98288 which includes a fuse 25A, fuse holder and relay, and to provide the new wiring/installation information.

EM20705
Relay

Kit #EM98288

- EM98287 Spade fuse 25 amp
- EM98066 Holder, fuse
- EM515799 Relay assembly

Relay of
EM515799



K1 RELAY
BOTTOM VIEW