Technical Information

Product Group: RIDE-ON TROWELS
Model: HTXD6i;STXD6i;HTXG6DF;STX6H;HTX6H

This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

MCU FIRMWARE AND PARAMETER DOWNLOADING

This document is to outline the procedure to install the firmware and parameter files onto a blank MCU received as a service part.

Prior to following this procedure must have the following:

- Plus+1 Guide Service Tool software installed
- Correct WST file for the Ride-On Trowel model being worked on.
- Current Firmware and Parameter files according to the model being worked on.
- CAN150 Gateway interface cable.

Go to http://service.multiquip.com/whiteman-service-tool.html files download and additional information.

1. Click "Main Screen" from the System Navigator menu then click "Machine Setup" button to get to the Machine setup page.

NOTE: THE IMAGES ON THIS DOCUMENT WERE FROM A WST FILE 22708RevE USED ON MODEL # HTXD6I AND STXD6I. FOR OTHER MODELS THIS MAY APPEAR DIFFERENT.


2. Click "Download to Firmware to MCU"

Technical Information

Product Group: RIDE-ON TROWELS
Model: HTXD6i;STXD6i;HTXG6DF;STX6H;HTX6H

This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

3. Find the ."lhx" file on your computer. Currently the name of this file is 30441100.lhx. Highlight the file and Hit "Open"

4. Hit "Next" at the "Download File to ECU –" window.

Technical Information

Product Group: RIDE-ON TROWELS
Model: HTXD6i;STXD6i;HTXG6DF;STX6H;HTX6H

MULTIQUIP®

This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

5. The Application type change warning is triggered because no software is currently loaded on the controllers so it has nothing to compare to, Hit "Next".


6. It will now ask to "Confirm new application type". Use the *confirmation codes based on model to proceed.

*confirmation codes:
HTXD6i,STXD6i = 22707
HTXG6DF = 42003
HTX/STX6H = 42642
STXDF = 43048

Technical Information
Product Group: RIDE-ON TROWELS
Model: HTXD6i;STXD6i;HTXG6DF;STX6H;HTX6H

This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

7. Add the application type and click "OK". It will give you the regular download screen with the status saying 'Application type changed'.


8. Click "Start Download"

Technical Information

Product Group: RIDE-ON TROWELS
Model: HTXD6i;STXD6i;HTXG6DF;STX6H;HTX6H

This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

9. The normal load screen with run for about 30 seconds

10. A "Download successful" should come up when complete

Technical Information

Product Group: RIDE-ON TROWELS
Model: HTXD6i;STXD6i;HTXG6DF;STX6H;HTX6H

This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

11. Click "Stop Logging" first then Click "Download and all parameters value" to download the parameter set and calibrate