




This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

FORWARD/REVERSE CONTROL LEVER

MQ PART# 513323

It has been noticed when replacing this lever the adjustment for reverse travel is limited due to the adjusting bracket mounted in the incorrect position.

When replacing the travel lever for the AR-13 series roller, notice there is an adjusting bracket on the lever assembly.



NOTE: The bracket may need to be rotated 180° this will allow more travel adjustment at the lever.

Control Lever

