


This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

## **ROCKER ARM BEARING FELT PADS**

The cam rocker arm felt pads are part of maintenance and should be checked regularly.







The cam rocker arm felt pads are part of maintenance and should be checked regularly.