

JOHN DEERE'S VALVES ADJUSTMENT SERVICE INFORMATION

John Deere's service and maintenance interval chart requires checking and adjusting the engine valves at 3000 hours of service. This service should only be performed by an authorized John Deere service provider.

- Not following the service intervals may lead to poor engine performance and even engine and valve train damage.
- Incorrect valve adjustment problems can be compounded with carbon build up from engine light loading resulting in damage even prior to 3000 engine hours.



Catastrophic engine damage



Valve bridge dropped

All John Deere recommended service intervals are available with the units provided with engine owner's manual.

DCA70SSJU4i and DCA125SSJU4i uses the **4045** John Deere engine.

DCA150SSJU4F and DCA220SSJU4F uses the **6068** John Deere engine.

DCA300SSJU4F use the **6090** John Deere engine.



For a list John Deere service provider near you visit <https://dealerlocator.deere.com/servlet/> or contact Multiquip technical support team @ 800-835-2551