

This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

PREHEAT LAMP DOES NOT LIGHT





ILLUSTRATION FROM DLW-400ES-ESA PARTS AND OPERATIONS MANUAL