



SYMBOL	PARTS NAME
Ar	Armature Winding
Fg	Field Winding
EXW1~2	Excitation Winding
V	AC Voltmeter (120V/240V)
Re1~3	Rectifier
CON1	Receptacle L14-30R HBL2710
CON2	Receptacle L6-20R HBL2320SR
CON3	Receptacle L5-30R HBL2610
CON4~5	Receptacle 5-20R GF20LA GFCI (LED)
CB	Circuit Breaker UPM-2 35A
CB1	Circuit Breaker 1CS30-2R 30A
CB2	Circuit Breaker 1CS30-2R 20A
CB3	Circuit Breaker 1CS30-1 30A
CB4~5	Circuit Breaker 1CS30-1 20A
SW1	Idle Control Switch ET115A12
SW2	Operation Switch ET425N12
SW3	Starter Switch ST-403
RC	Idle Control Device ND-80B
S	Idle Control Solenoid
Ry	Relay
F1, F2	Fuse 10A
GR	Ground Terminal T-3830
R	Resistor
H	Hour Meter N430

COLOR CODE			
CODE	WIRE COLOR	CODE	WIRE COLOR
B	BLACK	R	RED
L	BLUE	W	WHITE
BR	BROWN	Y	YELLOW
G	GREEN	LB	LIGHT BLUE
GR	GRAY	LG	LIGHT GREEN
V	VIOLET	O	ORANGE
P	PINK		

GAC-9.7HEA
CANADA - WIRING DIAGRAM