Model: EHTX44Y5,HTXD6i,STXD6i

This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

FUEL SCREEN FILTER CHANGE

The fuel screen filter has been changed with a design that is less restrictive and will filter out large in tank contaminants.

This change was made to reduce field issues with the screen filter becoming restricted.

The fuel system still utilizes a Yanmar fuel/water separator and the main Yanmar fuel filter.

THIS CHANGE IS EFFECTIVE BEGINNING WITH S/N: SF002800

OLD SCREEN FILTER MQ PART # 12010

NEW SCREEN FILTER MQ PART # 29677



