e-mail or call the Service Technical Support Group 800 478-1244

## SPIDER PLATE IMPROVEMENT

HTXD6i & STXD6i models with six blade spider MQ Part # 23341 (spider assembly)

A change was made to the spider plate to strengthen the area shown below Production change begins with serial # 1204

- The radius cut where the spider hub meets the spider legs has increased to 3/16"
- Spider serial numbers are stamped into the top of the spider hub.

This photo shows the OLD RADIUS cut

**NOTE**: The spider is shown without the sleeve installed on purpose, to allow the radius to be shown for this document. The serial number can be used to determine if the spider has the new radius cut.

TI\_HTXD6i\_STXD6i\_Spider\_Plate\_Improvment

This photo shows the NEW RADIUS cut.