

This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

NEW IMPROVED CRANK ARM LOCK

The new Crank Arm Lock prevents having to re-drill a 1" cotter pin hole every time a nun-plate is re-adjusted and re-tensioning is needed.

MQ PART NUMBERS

Part # 518555 - Adjustable Locking Arm Part # 518556 - Spacer Part # 492394 - Bolt HHCS 1/2" NC x 1" G5 Part # 492626 - Lock Washer



