

PISTON CUP ASSEMBLY MODIFICATION

The new piston cup assembly now features a slightly tighter tolerance and extended cup life.

Effective Machine Serial #H090088 (September 2017)

