

NEUTRAL JUMPER CONNECTOR

Several occasions have been noted where only two of the four lamps come on after performing a gen-end conversion or replacement. The cause in these cases was found to be from a Neutral Jumper Connector being left out from the TB1 strip during reassembly. The jumper connector completes the Neutral connection.

