



This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

ADDITION of SECONDARY ACCUMULATOR SPRING

Background: In some instances the MVH206 may not respond to movement of the forward/reverse travel lever.

Solution: Mikasa has determined this may be corrected with the addition of a secondary accumulator spring to the hand pump of the MVH206 – Series reversible plate compactors. This change is effective with production machines beginning with serial numbers S-1228 and higher.

It is recommended that **PART# 4662-18100** be used in conjunction with the original spring to improve travel lever response. The secondary spring sits *inside* the spring provided with the original assembly.

