the Service Technical Support Group 800 478-1244.

**JLTIQUIP** 

Product Group: TROWELS

Model: MECHANICAL RIDE-ON

PILLOW BLOCK BEARING PRODUCTION CHANGE

This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call

The pillow bearings for the cross shaft assemblies on Mechanical Ride-On trowels are now Timken or Dodge bearings.

## AFFECTED MODELS: HHN, HHX, HTN

MQ Part # 32484 is now the new service bearing that replaces MQ Part # 10337. The Timken/Dodge bearing serves as a direct replacement from the previous brand (JIB or Browning).



**NEW STYLE BEARING** (TIMKEN/DODGE)



## Previously use bearings:



The Browning bearing were used from production date of 5/24/2012 beginning Serial # UE0207330



IMPORTANT: The shim (MQ Part #11773) on this old style JIB bearing is NO LONGER used with new bearing.

