



This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

CORRECT PISTON RING REPLACEMENT

Commonly forgotten when rebuilding the ROBIN EC12 engine is the piston ring placement.

Assemble rings in order of the second ring and then the top ring.


TOP RING: Has chromium plated surface (looks white or light grey in color).

SECOND RING: Has a parkerized surface (looks dark in color).

ROBIN EC12 Engine used on the MQ RAMMER model - **MT75HS**

PISTON - MQ PART# 1612340101

RING SET - MQ PART# 1612350107



NOTE: Notice the angle on the top side of the top ring, ring will only insert with angle in this position.

