

Service Bulletin No. CV20051114
Subject: Decal Replacement
Model: SV-2 Series
Product Group: Concrete Vibrators
Date: November 14, 2005

SERVICE BULLETIN**Group: CV**

 Mandatory **Information** **Recommended Change**

Series/Parts Affected:
STOW SV-2 Series Vibrators

Machines Affected

Selected units within serial number range: BH4504161 – BH4504338

SERVICE INFORMATION

<p>Description of Problem: Some SV-2 vibrator motors were erroneously labeled as SV-1 motors. This may result in the unit being seen as underpowered and cause problems when ordering service parts.</p>

<p>The model number of the unit appears in two locations on the motor: a (red) SV-1 decal and the serial number plate. There is no problem with the serial number data plate.</p>

<p>Corrective Action: A replacement decal is being sent to all dealers with affected units. For best results, completely remove the SV-1 decal from the vibrator housing. Make certain the housing is clean and dry before applying the replacement decal to ensure proper adhesion.</p>

PARTS INFORMATION

Quantity	Part #	Description	Remarks
1	30166-004	Decal, SV-2	

WARRANTY INFORMATION

<p>Campaign: Reference No. – 0511-0047</p>

<p>There will be no labor reimbursement for this action.</p>
