



This bulletin is provided for technical reference and service related updates. If you have any questions, comments or do not wish to receive these e-mails, please reply to this e-mail or call the Service Technical Support Group 800 478-1244.

## FUEL FILTER CHANGE

We have increased the fuel system protection with by adding a 20 micron fuel filter after the fuel pump and relocating the 40 micron filter between the tank and pump.

Production change from Serial Number: **TA 0207610**

