



Service Bulletin

HHNG5 Throttle Retrofit Kit

| | | |
|---|---|---|
| Product Group: Ride-On Power Trowels | Date Issued: 06/20/13 | Service Bulletin No. TR20130613 |
| Bulletin Type <input checked="" type="checkbox"/> Mandatory <input type="checkbox"/> Information Only <input type="checkbox"/> Recommended Change | Models/Series Affected: HHNG5 S/N TA0207069, TA0207610, TA0207613 S/N TC0207696 ~ TC0207706 S/N TD0207707 ~ TD0207722 S/N TD0207725 ~ TD0207728 S/N TD0207730 S/N TD0207732 ~ TD0207733 S/N TD0207735 ~ TD0207737 S/N TD0207739, TD0207742, TD0207745, TD0207750 S/N TF0207796 | |

| |
|--|
| Details |
| Problem: The <i>plastic slide body</i> on the engine throttle control bracket may break or become deformed due to heat from the muffler. |
| Solution: Replace existing plastic slide body with a <i>brass slide body</i> . Reference HHNG5 Throttle Retrofit Kit Instructions P/N 30087. |

| |
|---|
| Warranty Information |
| Campaign Reference No. 20130620 |
| Please contact Chris Fairchild or Wendy Sanchez @ 1-800-421-1244 for warranty claim number and warranty form. |
| Labor Allowance: Flat Rate to install – 1 hour. |



Service Bulletin

HHNG5 Throttle Retrofit Kit

HERE'S HOW TO GET HELP

PLEASE HAVE THE MODEL AND SERIAL
NUMBER ON-HAND WHEN CALLING

UNITED STATES

Multiquip Corporate Office

18910 Wilmington Ave. Tel. (800) 421-1244
Carson, CA 90746 Fax (310) 537-3927
Contact: mq@multiquip.com

Service Department

800-421-1244 Fax: 310-537-4259
310-537-3700

Technical Assistance

800-478-1244 Fax: 310-943-2238

MQ Parts Department

800-427-1244 Fax: 800-672-7877
310-537-3700 Fax: 310-637-3284

Warranty Department

800-421-1244 Fax: 310-943-2249
310-537-3700

MEXICO

MQ Cipsa

Carr. Fed. Mexico-Puebla KM 126.5 Tel: (52) 222-225-9900
Momoxpan, Cholula, Puebla 72760 Mexico Fax: (52) 222-285-0420
Contact: pmastretta@cipsa.com.mx

CANADA

Multiquip

4110 Industriel Boul. Tel: (450) 625-2244
Laval, Quebec, Canada H7L 6V3 Tel: (877) 963-4411
Contact: jmartin@multiquip.com Fax: (450) 625-8664

UNITED KINGDOM

Multiquip (UK) Limited Head Office

Unit 2, Northpoint Industrial Estate, Tel: 0161 339 2223
Globe Lane, Fax: 0161 339 3226
Dukinfield, Cheshire SK16 4UJ
Contact: sales@multiquip.co.uk

© COPYRIGHT 2013, MULTIQUIP INC.

Multiquip Inc, the MQ logo and the Whiteman logo are registered trademarks of Multiquip Inc. and may not be used, reproduced, or altered without written permission. All other trademarks are the property of their respective owners and used with permission.

This manual MUST accompany the equipment at all times. This manual is considered a permanent part of the equipment and should remain with the unit if resold.

The information and specifications included in this publication were in effect at the time of approval for printing. Illustrations, descriptions, references and technical data contained in this manual are for guidance only and may not be considered as binding. Multiquip Inc. reserves the right to discontinue or change specifications, design or the information published in this publication at any time without notice and without incurring any obligations.

Your Local Dealer is:

