



PISTON CUP ASSEMBLY MODIFICATION

The new piston cup assembly now features a slightly tighter tolerance and extend cup life.

Effective Machine Serial # H090088 (September 2017)

New Cup Identification: Color Yellow



(New)
Face Plate
Part # 806441TT



(New)
Piston Cup
Part # EM98050Y



(New)
Bronze Ring
Part # EM806440



(New)
Felt Holder
Part # EM806439



(New)
Piston Head Adaptor
Part # EM806438